
From: Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFF136]
Sent: 5/26/2015 4:28:27 PM
To: Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]
CC: John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]
Subject: RE: Ash Pond ABC inspection 05/26/15
Attachments: 20150526155726838.pdf

Attached.

No Discharge at C Pond. Standing water around weir and Southeastern edge of Pond C and into center of C Pond beginning to recede. Water level inside bottom of weir is below pipe.

There was some seeping and dripping inside C Pond discharge weir, above the "board", and in both corners. Oddly enough, the standing water level is lower and no appreciable rainfall has been received in the past several days.

Standing water behind sand-bags at 'A' was less and standing water at the toe of the slope in this area was less. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water, but also less than previous inspection. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

No precipitation over the last several days.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)